



POWER CIRCUIT DIAGRAM



POWER P.C.BOARD



LOCATION GUIDE

BC101	D3	F6	L101	B5	R127	G3	
BC102	D5	E6	L102	B3	R128	F1	
BD101	B5	HE	L121	G4	R129	F1	
C101	B2	HE	L122	G3	R130	G1	
C103	B4	GE	L123	G4	R131	E6	
C104	B6	HE	L124	G4	R132	E6	
C106	C6	HE	L125	F2	R133	E6	
C105	D2	HE	L126	G5	R134	G2	
C109	D3	D7	L127	G6	R135	G2	
C107	C4	D3	L128	G3	R136	G2	
C108	D4	D3	P170	15	R137	HE	
C109	C4	D4	P100	F7	R138	HE	
C110	A4	D7	P101	H1	R139	H2	
C111	D6	D2	F4	P1M01	G7	R140	G2
C112	D6	D4	D7	P1101	13	R141	H1
C113	G4	F3	F5	PW101	C1	R142	H2
C114	G4	G4	F2	Q10	G2	R143	F2
C115	D4	D26	F2	Q11	H2	R145	H2
C116	D5	D5	Q2	Q22	H2	R146	F3
C117	D6	Q6	Q3	Q23	F2	R147	H3
C118	C6	Q30	E3	Q24	G2	R149	H1
C119	D6	Q31	F3	R100	C1	R150	H4
C120	H3	Q34	G2	R101	C2	R151	G6
C121	E4	Q35	F4	R102	C2	R152	H5
C122	F3	Q54	H4	R103	D2	R153	H6
C123	F4	FH01	B1	R105	D3	R154	15
C124	G3	FH02	B2	R106	D4	R159	H5
C125	H5	IC101	C3	R107	E1	R160	G4
C126	F4	IC102	E4	R109	C3	R161	F4
C127	G4	IC103	E4	R110	C4	R162	E6
C128	H4	IC104	C5	R111	C5	R163	E6
C129	H5	IC105	D7	R112	D4	T101	E3
C130	F3	IC106	E7	R113	D5	T102	E5
C131	F2	IC151	F5	R114	C6	TH01	B6
C132	F1	IC153	H3	R115	D6	V101	B2
C133	E1	IC154	16	R121	F3	ZD101	D6
C134	15	IC156	H4	R122	E4	ZD102	C6
C136	F2	IC158	F6	R123	E4	ZD103	C3
C137	F2	IC159	HE	R124	F4	ZD104	D4
C138	G5	IC160	GE	R125	F4	ZD151	G1
C139	F6	J101	H5	R126	F4	ZD152	14